


# LIRA DISTRICT: Safe Water Accessibility and Water Source by Sub-County (September 2008)



### Legend

**Water Source Status**

- Abandoned (Red dot)
- Fully Operational (Green dot)
- Partially Operational (Blue dot)
- Temporary Down (Pink dot)

Lake and Water Body (Blue area)  
 Motorable Road (Red line)

**Safe Water Cover %pop08**

- 31.00 - 50.00 (Light Yellow)
- 50.01 - 60.00 (Yellow)
- 60.01 - 75.00 (Orange)
- 75.01 - 134.21 (Dark Brown)

District (Grey outline)  
 Sub-County (White outline)

**Pie (Safe Water Cover Ratio)**

- Cover (Yellow)
- Not Cover (Red)

Per Capita Access (Litres per person per day) (Grey box with value)

**Notes:**

- Pie size is weighted by total projected population of 2008 in the sub-county.
- Safe water cover rate calculated based on 2008 projected total population by sub-county.

**Data Sources:**

- Admin Boundaries - UBOS 2006
- Road Network - FAO
- Safe Water Access and Water Source - District Water Office, Sep 08
- Projected Population - UBOS 2008

Please contact District Water Office in Lira district directly for more information on thematic details.

*This map is a work in progress. Please contact the IMU/OCHA as soon as possible with any corrections.*

**Map Disclaimer:**

The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.

**Draft**

0 2.5 5 10 Kilometers

Map Prepare: 08 Sep 2008 (IMU/UNOCHA, Kampala)  
 File: UG-LIRA-WASH-01\_A3\_08Sep08\_Lira District Safe Water Accessibility and Water Source by Sub-County